

Page 9, lines 12-18, replace the paragraph as follows:


The vibration actuator of Fig. 5 is different from that of Figs. 1A and 1B in that the L-shaped portion 23 of the vibration member 18 in Fig. 1A is replaced by a U-shaped portion 36. With this structure, the coil 17 is fitted in the U-shaped portion 36 and kept in contact with the vibration member 18 at three surfaces. Therefore, the coil 17 is hardly released from the vibration member 18 as compared with the L shape illustrated in Figs. 1A or 4 and providing two surfaces as contact surfaces. Thus, this structure is highly reliable.

IN THE DRAWINGS:

Please amend Fig. 6A as indicated in red on the accompanying copy thereof.

Upon approval, a new corrected Formal Drawing will be supplied in due course.

Respectfully submitted,


Robert P. Michal, Reg. No. 35,614
for Leonard Holtz, Reg. No. 22,974

Frishauf, Holtz, Goodman, Langer & Chick, P.C.
767 Third Avenue - 25th Floor
New York, New York 10017-2023
Tel. No. (212) 319-4900
Fax No. (212) 319-5101
LH:sp


01933
PATENT TRADEMARK OFFICE